

3- ARS (BRS Comfort)			
1	ARS 80 Comfort	80	67 413
2	ARS 100 Comfort	99	85 388
3	ARS 120 Comfort	120	87 561
4	ARS 150 Comfort	150	97 739
5	ARS 180 Comfort	180	115 161
6	ARS 200 Comfort	210	119 025
7	ARS 250 Comfort	250	169 637
8	ARS 300 Comfort	315	176 813
9	ARS 400 Comfort	420	201 239
10	ARS 500 Comfort	520	284 625
11	ARS 600 Comfort	630	345 000
12	ARS 700 Comfort	700	374 325
13	ARS 830 Comfort	830	402 512
14	ARS 1000 Comfort	1000	431 250
3- RS (BRS Comfort) ...BM			
1	BRS Comfort 80	82	97 773
2	ARS 100 (BRS 100 Comfort)	99	99 774
3	ARS 150 (BRS 150 Comfort)	150	108 675
4	ARS 200 (BRS 200 Comfort)	220	141 312
5	ARS 220 (BRS 220 Comfort)	240	156 975
6	ARS 250 (BRS 250 Comfort)	270	161 598
7	ARS 300 (BRS 300 Comfort)	300	195 201
8	ARS 350 (BRS 350 Comfort)	350	210 450
9	ARS 400 (BRS 400 Comfort)	400	252 126
10	ARS 450 (BRS 450 Comfort)	450	271 688
11	ARS 500 (BRS 500 Comfort)	500	284 039
12	ARS 600 (BRS 600 Comfort)	600	299 012
13	ARS 700 (BRS 700 Comfort)	700	365 424
14	ARS 800 (BRS 800 Comfort)	800	385 676
15	ARS 1000 (BRS 1000 Comfort)	1000	416 312
16	ARS 1200 (BRS 1200 Comfort)	1200	502 562





**Торговый дом
Коростенского завода
теплотехнического оборудования**



(067) 275-81-82, (063) 522-25-95, e-mail: tdkzto@gmail.com, www.tdkzto.com.ua




3-		ARS(BRS Comfort)...LM		c
1	ARS 50 L (BRS 50 Comfort L)	48	77 349	
2	ARS 80 L (BRS 80 Comfort L)	80	97 739	
3	ARS 100 L (BRS 100 Comfort L)	99	100 050	
4	ARS 150 L (BRS 150 Comfort L)	150	108 951	
5	ARS 200 L (BRS 200 Comfort L)	220	141 588	
6	ARS 220 L (BRS 220 Comfort L)	240	157 251	
7	ARS 250 L (BRS 250 Comfort L)	250	161 874	
8	ARS 300 L (BRS 300 Comfort L)	300	195 512	
9	ARS 350 L (BRS 350 Comfort L)	350	210 726	
10	ARS 400 L (BRS 400 Comfort L)	420	252 437	
11	ARS 500 L (BRS 500 Comfort L)	500	284 349	
12	ARS 600 L (BRS 600 Comfort L)	620	299 288	
13	ARS 700 L (BRS 700 Comfort L)	700	365 700	
14	ARS 800 L (BRS 800 Comfort L)	830	385 986	
15	ARS 1000 L (BRS 1000 Comfort L)	980	416 588	
16	ARS 1200 L (BRS 1200 Comfort L)	1200	502 838	
17	ARS 1500 L (BRS 1500 Comfort L)	1450	572 424	
18	ARS 2000 L (BRS 2000 Comfort L)	1980	805 299	
19	ARS 2500 L (BRS 2500 Comfort L)	2480	877 163	



**Торговый дом
Коростенского завода
теплотехнического оборудования**

(067) 275-91-82, (063) 522-25-95, e-mail: tdkzto@gmail.com, www.tdkzto.com.ua



001 () (70%)		3	156 389	
		15 35 80		
		1,65		
	:	3060 2880 1500		
		890		
	/	380/50		
002 (30%)		1,5	100 050	
		15 35 80		
		1,65		
	:	1300 3120 1350		
		390		
	/	380/50		
005 () ()		1,5	54 786 63 411 79 212	
		6 18		
		1,1 (100-900)		
		1,5 (1000-1500)		
		3,0 (2000)		
	:	2000 1600 1550		
		210/210/300		
/	380/50			

) – 22 400

3,5 2,2 (600) – 13 200,00
3 (600) – 13 800,00







**Торговый дом
Коростенского завода
теплотехнического оборудования**

(067) 275-91-82, (063) 522-25-95, e-mail: tdkzto@gmail.com, www.tdkzto.com.ua



/			()	()	
1	RS -12	12	14 076	18 630	
2	RS -16	15	14 281	18 728	
3	RS -20	20	17 291	20 010	
4	RS -25	24	18 544	21 160	
5	RS -32	32	21 987	25 990	
6	RS -42	42	23 790	28 520	
7	RS -50	48	25 712	32 085	
8	RS -65	65	30 638	37 260	
9	RS -80	80	51 750	62 100	

/			с		
1	BRS -12 -WM	12	57 960		: (Ø 6-10) ()
2	BRS -16 -WM	16	58 058		
3	BRS -20 -WM	20	59 340		
4	BRS -24 -WM	24	60 490		
5	BRS -32 -WM	32	66 010		
6	BRS -42 -WM	42	67 965		
7	BRS -50 -WM	50	71 415		
8	BRS -65 -WM	65	73 945		
9	BRS -80 -WM	80	78 430		



**Торговый дом
Коростенского завода
теплотехнического оборудования**



(067) 275-81-82, (063) 522-25-95, e-mail: tdkzto@gmail.com, www.tdkzto.com.ua

W					
1	ARS 550 W	10 074	12 351	18 113	23 943
2	ARS 550 W	10 350	14 249	19 976	25 737
3	ARS 800 W	11 799	13 662	19 424	26 600
4	ARS 800 W	12 075	17 250	21 563	27 324
5	ARS 1000 W	15 249	20 907	25 220	30 981
6	ARS 1200 W	16 388	22 046	26 358	32 120
7	ARS 1500 W	20 700	24 150	28 463	34 224
8	ARS 2000 W	25 875	30 188	34 500	40 262
9	ARS 2300 W	28 463	34 500	38 813	44 574
10	ARS 3200 W	35 639	41 400	45 713	51 474
11	ARS 4000 W	42 849	55 511	59 823	65 585
12	ARS 5000 W	56 063	69 000	73 313	79 074
G					
1	ARS 5000 G	57 201	70 449	*	*
2	ARS 10000 G	70 311	84 698	*	*
3	ARS 15000 G	97 187	118 749	*	*
4	ARS 20000 G	118 128	139 691	*	*



+ 20%

*



Торговый дом
Коростенского завода
теплотехнического оборудования

(067) 275-91-82, (063) 522-25-95, e-mail: tdkzto@gmail.com, www.tdkzto.com.ua



– 800 (800-1000)		_____
	/	6000
	, %	85...98
	.	147
	:	
*	*	1605*1090*3500
	:	340
– 600 (450-700)		_____
	/	4000
	, %	85...98
	.	147
	:	
*	*	1160*1090*2972
	:	260
– 500 (250-400)		_____
	/	3000
	, %	85...98
	.	147
	:	
*	*	1158*1090*2646
	:	260
– 200 (100-200)		_____
	/	2000
	, %	85...98
	.	147
	:	
*	*	1000*1090*2316
	:	200



Торговый дом
Коростенского завода
теплотехнического оборудования

(067) 275-91-82, (063) 522-25-95, e-mail: tdkzto@gmail.com, www.tdkzto.com.ua



- - 1500 (1300-1500)		-	
	/	12700	48 887
	, %	85...90	
	.	147	
	:		
*	*	1160*1100*4550	
	:	420	
- - 800 (800-1200)		-	
	/	8100	48 300
	, %	85...98	
	.	147	
	:		
*	*	1200*1072*3520	
	:	340	
- - 600 (500-700)		-	
	/	6100	42 987
	, %	85...98	
	.	147	
	:		
*	*	1200*1072*3050	
	:	260	
- - 400 (250-400)		-	
	/	3000	39 261
	, %	85...98	
	.	147	
	:		
*	*	1158*1090*2646	
	:	260	
- - 200 (100-200)		-	
	/	2000	38 640
	, %	85...98	
	.	147	
	:		
*	*	1000*1090*2316	
	:	200	